



Cleaning/Maintenance Report

Property
Inspection Date
Inspected By

200 Hampden Road, Nedlands 6009
Friday, 3 June 2016
Nicky



Front Gardens	Front fence requires painting. See photo
Fence	Front fence requires painting
Rear Gardens	
Garage	
Entry/Exterior	Render crumbling on veranda wall
Kitchen/Meals	Pantry sensor light not working
Lighting	Pantry sensor not working
Cupboard	Cupboard door requires fixing
Theatre	Carpets require cleaning
Lounge	
Ceiling Fan/Air Conditioner	Aircon requires servicing
Bathroom 1	
Bathroom 2	
Bedroom 1	
Bedroom 2	
Bedroom 3	
Dining	
Toilet	
Laundry	
Security/Safety	



Front Gardens
Taken : 03/06/2016



Entry/Exterior
Taken : 03/06/2016

