



Cleaning/Maintenance Report

Property 200 Hampden Road, Nedlands 6009
Inspection Date 11 Oct 2019
Inspected By Jeremy Emms

Front Gardens	Front fence requires painting. See photo
Fence	Front fence requires painting
Entry/Exterior	Render crumbling on veranda wall
Kitchen/Meals	Pantry sensor light not working
Lighting	Pantry sensor not working
Cupboard	Cupboard door requires fixing
Theatre	Carpets require cleaning
Lounge	
Ceiling Fan/Air Conditioner	Aircon requires servicing

Photos

Front Gardens
Taken : 11/10/2019



Entry/Exterior
Taken : 11/10/2019

