

PIM Inspections Pty Ltd 200 Infinity Loop Perth WA 6000

Phone: 1300 668 594 Lic. No. 1234556 ABN 11 222 333 444

Smoke Alarm Inspection Report

Site Details

Address 200 Hampden Road, Nedlands 6009

Work Order #45027

Representative Name Mr Compliance - Smoke Alarm

Important Details

This test and works have been carried out to help landlords meet the requirements of:

Building Legislation Amendment (Smoke Alarms) Act 2005

Environmental Planning and Assessment Amendment (Smoke Alarms) Regulation 2006

Building Code of Australia (BCA) Section 3.7.2.2

Residential Tenancies Regulation 2019

Residential Tenancies Act 2010

A landlord must carry out annual check to ensure all smoke alarms installed at the property are in working order, replace a removable battery in all smoke alarms in the period specified by the smoke alarm manufacturer (for a removeable lithium battery), or otherwise annually and repair or replace a smoke alarm with a new smoke alarm within 10 years from the manufactured date, or earlier if specified by the smoke alarm manufacturer.

PIM Inspections Page 1 of 3



Smoke Alarm 1

Smoke Alarm Type/Position		CR456 positioned on the ceiling
Smoke Alarm Expiry Date		10/10/21
Battery Replaced At Time Of Inspection	Yes	





Smoke Alarm 2

Smoke Alarm Type/Position		SM12B lower floor ceiling
Smoke Alarm Expiry Date		21/12/21
Battery Replaced At Time Of Inspection	Yes	
Smoke Alarm Passed Smoke Test	No	Battery dead





Smoke Alarm 3

Smoke Alarm 4

Smoke Alarm 5

Switchboard Review

All working and safety switches clean and working

PIM Inspections Page 2 of 3



Switchboard Review



Compliance

All of the above works and assessment have been carried out to ensure this property complies with Building Legislation Amendment (Smoke Alarms) Act 2005

Environmental Planning and Assessment Amendment (Smoke Alarms) Regulation 2006

Building Code of Australia (BCA) Section 3.7.2.2

Residential Tenancies Regulation 2019

Residential Tenancies Act 2010

Does This Property Comply

Yes

Signed By: Mr Compliance - Smoke Alarm Signature

M Snoke

Date: 24 Sep 2020

PIM Inspections Page 3 of 3